CAUTION LABEL ATTACHMENT POSITION

After using a degreasing agent to clean the surfaces of the body where the caution labels will be attached, attach the caution labels to the positions shown in the illustration.

HINT:

1) *Attach each caution label with its orientation the same as the numbers shown in the illustration.*
2) *Make sure the caution label is not attached over a spot weld.*
3) *When attaching the caution label, make sure not to touch the label's adhesive surface.*
4) *To prevent the edges of the caution label from peeling, apply extra pressure to the label's periphery.*
5) *If the work area's temperature is 5° C or less, the caution label's adhesive will deteriorate. It is recommended that you heat the label to 20 to 40° C.*




123
Fuel Label
Side Air Bag Caution Label
[LH]
Mercury Information Label (U.S.A.)
Tire Pressure Label
Side Air Bag Caution Label
Certification Reguration Info Label
[RH]
Name Plate (China)
Side Air Bag Caution Label
Side Air Bag Caution Label (China)
F25928